

185 785

Belknap Freeman, PE
119 Hickory Ln.
Rosemont, PA 19010-1017

DEPT. OF TRANSPORTATION
DOCKETS

02 AUG 20 PM 12:05

1-610-527-0146

U.S. Department of Transportation
Docket Clerk DOT
Central Docket Management Facility
Nassif Building, Room PL-401
400 7th Street, SW
Washington, DC 20590-0001

Supplemental Response To:

Waiver Docket FRA 2002-12836 - 5

A previous Docket Response dated 21 August 2002 (approximately 57 pages) was previously submitted as **FRA 2002-12113**. It has been brought to my attention, that it should have been captioned **FRA 2002-12836**. Please arrange to place the original submission under the correct captioned Docket Number.

As indicated by the extract of instructions as previously published by the FRA Notice (67FR49386), the Docket Number 2002-12113 was employed as cited in the text of the Notice:

All communications concerning these proceedings should identify the appropriate docket number (e.g., Waiver, Petition Docket Number FRA-2002-12113) and must be submitted to the Docket Clerk, DOT Central Docket Management Facility, Room PL-401, Nassif Building, Washington, DC, 20590-0001.

"Oops" -- In the instructions, that was intended only as an example; however, in the frame of the entire paragraph, it is easy to be construed as part of the instruction. As the Docket Number to be employed in any response was printed elsewhere in the same Notice, the question arises as to why not having employed the **correct number in the instructions** rather than an example???



Belknap Freeman, PE
26 August 2002